



Heavy Duty, Alkaline Concentrate Effectively Penetrates and Removes Carbonized Residues, Grease and Oil from Hoods, Vents, Walls, Ceilings, and Equipment Surfaces.

FOAMING with **BLITZ** is the best method to remove heavy soils and deposits from vertical or overhead surfaces. Dilution ratios with Tank Foamer or Barrel Foamer: Use 1/2 oz. to 3 oz per gallon of hot water.

SOAKING OR LOW PRESSURE SPRAY: Use 2 to 4 ozs. per gallon warm water (150° TO 180°F).

STEAM CLEANING: Use 1 to 2 ozs. per gallon hot water.

HAND BRUSH OR BUCKET METHOD: Use 4 to 6 ozs. per gallon warm water (120° to 150°F).

The Quality Chemical Company 
VentureTECH
CORPORATION
10720 Lexington Drive • Knoxville, TN 37932
(865) 966-2532 • 1-800-826-4095 • FAX (865) 675-2532

BLITZ

HEAVY DUTY HOOD & VERTICAL SURFACE CLEANER

When using **BLITZ**, wear rubber or neoprene gloves. Do not use on aluminum and galvanized surfaces.

WARNING: Harmful if Swallowed: Corrosive to mouth, throat, esophagus and stomach. **Avoid Breathing Dust or Mists:** Corrosive to mucous membranes of the respiratory tract. **Avoid Eye Contact: Corrosive to eyes:** Burns eye tissue, cornea and retina. **Avoid Contact With Skin:** Corrosive to skin, causes severe & rapid burns, destructive to tissues on contact. **PERSONAL PROTECTION:** Wash thoroughly after use. Use with adequate ventilation. Chemical type goggles recommended. Impervious rubber or neoprene gloves recommended. **First Aid: INHALATION-**Get to fresh air. **EYES-**Flush with plenty of water for at least 15 minutes. See a physician. **INGESTION-** Do not induce vomiting. If conscious drink plenty of water. Call a physician or poison control center immediately. **SKIN-**Flush with plenty of water. **READ THE MATERIAL SAFETY DATA SHEET (MSDS) BEFORE USING THIS PRODUCT.**

KEEP OUT OF REACH OF CHILDREN

MEMBER
ISSA

HMIS RATING

Health Hazard	2	0	Fire Hazard	0	0	Reactivity	0
---------------	---	---	-------------	---	---	------------	---

0 - None
1 - Slight
2 - Moderate
3 - High
4 - Severe